

# **ASSEMBLYINSTRUCTIONS**


HLS5 / HLS5H





Tel: 020 3011 1014

Email: info@cloakroomsolutions.co.uk

# Drilling min. 65 mm **2**x Front view Horizontal drilling distance 400 mm Ø8 mm







### CLEANING INSTRUCTIONS STAINLESS STEEL

# **DRY CLEANING**

Normal dry cleaning is done with a soft, lint-free cloth. The frictional force should be kept as low as possible, otherwise the surface can change.

## **WET CLEANING**

Soft, lint-free cloths are also suitable for wet cleaning.

Dampen the cloth with water, wring it out and clean with a damp cloth.

## DANGER:

- 1. 1. In the case of heavy soiling, only use CHLORINE-FREE, MILD cleaning agents (it is essential to follow the manufacturer's recommendations and instructions).
  - 2. Never use abrasive cleaners and sponges.
  - 3. The friction force should be kept as low as possible, otherwise the surface may change.

# NOT SUITABLE FOR CLEANING

- 1. Detergents containing hydrochloric, chloric or hydrofluoric acid
- 2. Nonwovens containing abrasives
- 3. Materials made of unalloyed steel (e.g. steel brushes, steel wool, etc.)
- 4. Chrome, silver and brass polish
- 5. Furniture polishes

# AS A CLEANING AGENT, WE RECOMMEND THE PHOS STAINLESS STEEL CLEANER V2AR:

- 1. Remove coarse dirt.
- 2. Clean the surface with a slightly damp cloth.
- 3. Apply the PHOS stainless steel cleaner thinly.
- 4. Then polish the surface until it is dry. Please use only soft and lintfree towels and keep the frictional force as low as possible.

